6/A

DEPARTMENT OF PUBLIC HEALTH AND SOCIAL SERVICES
DIVISION OF ENVIRONMENTAL HEALTH

SCHOOL BUILDING INSPECTION REPORT

REASON		INSPECTION DATE	ESTABLISHMENT NAME	
Regular	✓	09 / 15 / 2016	MARIA ARTERO CATHOLIC PRE-SCHOOL & KINDERGARTEN	
Follow-up		INSPECTION TIME / HR. 45 MIN.	OWNER/OPERATOR MARIA ARTERO CATHOLIC PRE-SCHOOL & KINDERGARTEN	
Complaint		TRAVEL TIME HR. 20 MIN.	LOCATION AGANA HEIGHTS	
Investigation		SANITARY PERMIT # 160002480	PERMIT CATEGORY STATUS (Circle One) Permanent, Temporary, Current, Expired	ESTAB. TYPE SCHOOL
Other (Specify)				

Based on an inspection this day the items listed below identify violations in operation or facilities which must be corrected by the next routine inspection or such shorter period of time as may be specified by the Department. Failure to comply may result in cessation of your operations.

ITEM NO.	REMARKS	CORRECT BY: DATE
	A REGULAR, QUARTERLY INSPECTION WAS CONDUCTED TODAY. PREVIOUS INSPECTION DATED 03/16/2016 YIELDED A GRADE/RATING OF Ø/A. THE FOLLOWING VIOLATIONS WERE OBSERVED TODAY:	
14	EXIT DOORS FOR KINDERGARTEN CLASSROOM NOT SELF-CLOSING. EXITS SHALL BE EASILY ACCESSIBLE, SELF-CLOSING, AND SHALL OPEN OUTWARD TO FACILITATE EASE OF EGRESS ESPECIALLY IN CASES OF EMERGENCY.	10/15/16
29	HAND SOAP NOT PROVIDED FOR SINK IN THE RESTROOM NEXT TO THE PLAYGROUND. SOAP AND PAPER TOWEL SHOUL BE PROVIDED TO PROMOTE PROPER HANDWASHING.	COS
19	TABLE IN THE PLAYGROUND AREA IS IN DISREPAIR. FACILITY SHOUL BE PROPERLY MAINTAINED TO MINIMIZE PHYSICAL HAZARDS FOR KIDS.	10/15/16
	PICTURES OF VIOLATIONS WERE TAKEN.	
	ISSUED "A" PLACARD NO. 01732.	
	DISCUSSED THIS INSPECTION REPORT WITH PIC, SISTER ANITA ADDY.	

I have read and understand the above violation(s) and I am aware of the corrective measures to be taken.

*When any of the following items are cited above, they shall be corrected within ten days of the inspection: (01); (02); (23); (27); (31).

RECEIVED BY (Name and Title) Sr. Anita Addy, MMB 09/15/16

DEH INSPECTOR (Name and Title) VEILANI NAVARRO, EHO I